

# Sequence IIIG Update 11/11/02

- September 2002
  - Development Team visits
    - Central Foundry
    - Delphi
    - Engine Power Components
- Manganese Phosphating Process
  - Process control variables identified @ EPC
    - Recommended changes by Chemical Supplier greatly enhanced the process, but failed to produce desired consistency for test parts
- Switch to Dedicated Phosphating Supplier
  - Currently working with off-site supplier to:
    - Ensure process control generates desirable coating parameters
    - Ensure these parameters can be reproduced consistently
- We are not going back to MK camshaft processing!
- Testing is ongoing