

API Ballot Summary Sheet

10/21/2005

Ballot: 39-05: 620-278, RT of Repair Welds

AMS ID: 728

Start Date: 8/26/05

Closing Date: 10/7/05

Associate: Gordon Robertson

Coordinator: Gordon Robertson

Proposal:

Vote Results

<u>Voter</u>	<u>Company</u>	<u>Comments</u>	<u>Vote Results</u>			
			<u>Affirmative</u>	<u>Negative</u>	<u>Abstain</u>	<u>Did Not Vote</u>
134629	Nelson Acosta	HMT Inspection	No	X		
131617	Joel Andreani	Equity Engineering Group, Inc., The	No	X		
38921	Robert Annett	Alyeska Pipeline	No	X		
73074	Ronald Bailey	American Tank & Vessel, Inc.	No	X		
136219	Mark Baker	Baker Consulting Group, Inc.	No	X		
142888	Chris Bashor	Minnesota Pollution Control Agency	No	X		
134681	Ernie Blanchard	MOSAIC	No	X		
109375	Jerry Boldra	SBC Global	No	X		
22200	Dan Boley	DJA Inspection Services	No	X		
134782	Steve Caruthers	Tank Consultants, Inc.	No			X
154212	Gary Cavey	Conservatek Industries, Inc.	No	X		
7127	Earl Crochet	Kinder Morgan	No	X		
150217	Jody Day	Lide Industries, Inc.	No			X
142685	Domingo de Para	ExxonMobil	No	X		
133403	Jeffrey DeArmond	BP p.l.c. Whiting Refinery	No	X		
146748	Terry Delong	Terasen Pipelines (USA) Inc.	No		X	
135965	Kenneth Erdmann	Matrix Service Company	No	X		
105011	David Flight	Dow Chemical Company	Yes	X		
134870	Laurence Foster	Marathon Ashland Petroleum LLC	No	X		
134880	John Fumbanks	Pond and Company Inc.	No			X
115033	Alan Geis	Colonial Pipeline Company	No	X		
83689	Ty Hagen	Hagen Engineering International, Inc.	No	X		
136619	Robert Hendrix	Eastman Chemical Co	No	X		
70596	Marty Herlevic	James Machine Works, Inc.	No	X		
93133	Randy Kissell	TGB Partnership	No	X		
81918	Manfred Lengsfeld		No	X		
135014	John Lieb	Tank Industry Consultants, Inc.	No	X		

API Ballot Summary Sheet

10/21/2005

Ballot: 39-05: 620-278, RT of Repair Welds

AMS ID: 728

Start Date: 8/26/05

Closing Date: 10/7/05

Associate: Gordon Robertson

Coordinator: Gordon Robertson

Proposal:

136274	Thomas Lorentz	AEC Engineering, Inc.	No	X	
135072	Francis Maitland	Quense LLC	No		X
113545	James McBride	Petrex, Inc.	No	X	
139045	Craig Meier	ConocoPhillips	No		X
137255	Carl Mikkola	Enbridge Energy Partners, L.P.	No	X	
131185	Douglas Miller	Chicago Bridge & Iron Company(CB&I)	No	X	
69609	Bhana Mistry	TIW Steel Platework	No	X	
83736	John Mooney		No	X	
92212	George Morovich	TEMCOR	No		X
136286	Philip Myers	Chevron Corporation	No	X	
132210	David Nasab	Kellogg Brown & Root	No	X	
82544	John Oleyar	HMT, Inc.	No	X	
5193	Richard Pinegar	Cargill Inc.	No		X
102412	Roy Ralph	Petro-Canada	No		X
135169	Michael Richardson	International Paper	No	X	
73744	Bruce Roberts		No	X	
101360	Marilyn Shores	Sunoco Logistics	No	X	
126019	Larry Speaks	Mass Technology Corporation	No	X	
134314	Tearle Taylor	Flint Hills Resources	Yes		X
134325	Donald Thain	Shell Global Solutions (US) Inc.	No	X	
145034	Leith Watkins	Explorer Pipeline Company	No	X	
145896	Alan Watson	A.R. Watson, USA	No	X	
132209	Richard Whipple	Fluor, Inc.	No	X	

API Ballot Summary Sheet

10/21/2005

Ballot: 39-05: 620-278, RT of Repair Welds

AMS ID: 728

Start Date: 8/26/05

Closing Date: 10/7/05

Associate: Gordon Robertson

Coordinator: Gordon Robertson

Proposal:

	<u>Affirmative</u>	<u>Negative</u>	<u>Abstain</u>	<u>Did Not Vote</u>
Balloting Totals:	40	1	2	7

Total Responses:	43			
Total Ballots:	50			
Response Rate :	80%		Must be > 50%	
Approval Rate:	98%		Must be > 67%	
Consensus:	YES			

API Ballot Summary Sheet

10/21/2005

Ballot: 39-05: 620-278, RT of Repair Welds

AMS ID: 728

Start Date: 8/26/05

Closing Date: 10/7/05

Associate: Gordon Robertson

Coordinator: Gordon Robertson

Proposal:

API Template for Ballot Comments and Resolution

Ballot ID: 728	Date: November 3, 2005	Document: 39-05-620-278
----------------	------------------------	--------------------------------

	(1)	(2)	(3)	(4)	(5)	(6)	(7)
#	Voter/ Commenter	Company	Section No. (e.g. 3.1)	Type of comment	Comment (justification for change)	Proposed Change	Comment Resolution
1	Tearle Taylor	Flint Hills Resources		Technical	It appears that this ignores API 650 6.1.6 where you have to take two spots adjacent to the radiograph: 7.15.1.4 Sections of welds that radiography has revealed to be unacceptable shall be repaired in accordance with 6.15 and re-radiographed, repeating the original radiograph frequency and with examination procedure. IF I am reading this correctly this allows for a rejectable weld and no follow up. Should be 2 for 1, 4 for 2 etc.	Include that some verbage as per API 650 6.1.6	
2	David Flight	Dow Chemical Company	Proposed change to para. 7.15.1.2	Technical	The paragraph refers to "the inspector"...is this the Purchaser's Inspector, Tank Fabricator's Inspector or both?	I suggest the paragraph qualify who the inspector by stating so: 7.15.1.2 Before any welds are repaired, the radiographs shall be submitted to (Purchaser's)(Fabricator's) inspector.	

NOTE Columns 1, 2, 4, 6 are compulsory.

API electronic balloting commenting template/version 2002-12